

施工前照片1 Photos before construction1



樹幹周長 34 cm，樹木直徑 10 cm
Perimeter of tree trunk 34cm, diameter of the tree 10cm

施工前照片2 Photos before construction2



樹幹周長 67 cm，樹木直徑 21 cm
Perimeter of tree trunk 67cm, diameter of the tree 21cm

施工前照片1 Photos before construction1



樹幹周長 67 cm，樹木直徑 21 cm
Perimeter of tree trunk 67cm, diameter of the tree 21cm

施工前照片2 Photos before construction2



樹幹周長 41 cm，樹木直徑 13 cm
Perimeter of tree trunk 41cm, diameter of the tree 13cm

附件：施工照片 Attachments: Photos of construction

施工前照片1 Photos before construction1



樹幹周長 67 cm，樹木直徑 21 cm(?)

Perimeter of tree trunk 67cm,
diameter of the tree 21cm

樹幹周長 41 cm，樹木直徑 13 cm

Perimeter of tree trunk 41cm,
diameter of the tree 13cm

施工前照片2 Photos before construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工後照片1 Photos after construction1



施工後照片2 Photos after construction2



施工後照片1 Photos after construction1



施工後照片2 Photos after construction2



