

施工前照片1 Photos before construction1



樹幹周長 117 cm，樹木直徑 37 cm
Perimeter of tree trunk 117cm, diameter of the tree 37cm

施工前照片2 Photos before construction2



樹幹周長 113 cm，樹木直徑 35 cm
Perimeter of tree trunk 113cm, diameter of the tree 35cm

施工前照片1 Photos before construction1



樹幹周長 107 cm，樹木直徑 34 cm ㊸
Perimeter of tree trunk 107cm, diameter of the tree 34cm

施工前照片2 Photos before construction2



樹幹周長 97 cm，樹木直徑 30 cm ㊸
Perimeter of tree trunk 97cm, diameter of the tree 30cm

施工前照片1 Photos before construction1



樹幹周長 102 cm，樹木直徑 32 cm (5)
Perimeter of tree trunk 102cm, diameter of the tree 32cm

施工前照片2 Photos before construction2



樹幹周長 101 cm，樹木直徑 32 cm (6)
Perimeter of tree trunk 101cm, diameter of the tree 32cm

施工前照片1

Photos before construction1



樹幹周長 114 cm，樹木直徑 36 cm
Perimeter of tree trunk 114cm, diameter of the tree 36cm

施工前照片2

Photos before construction2



樹幹周長 138 cm，樹木直徑 43 cm
Perimeter of tree trunk 138cm, diameter of the tree 43cm

附件：施工照片 Attachments: Photos of construction

施工前照片1 Photos before construction1



施工前照片2 Photos before construction2



施工中照片1

Photos during construction1



施工中照片2

Photos during construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工後照片1 Photos after construction1



施工後照片2 Photos after construction2



施工後照片1

Photos after construction1



施工後照片2

Photos after construction2



施工後照片1 Photos after construction1



施工後照片2 Photos after construction2

