

施工前照片1 Photos before construction1



(修剪) 樹幹周長 101 cm，樹木直徑 32 cm)
(Trimming) Perimeter of tree trunk 101cm, diameter of the tree 32cm

施工前照片2 Photos before construction2



(修剪) 樹幹周長 80 cm，樹木直徑 25 cm)
(Trimming) Perimeter of tree trunk 80cm, diameter of the tree 25cm

施工前照片1 Photos before construction1



(修剪) 樹幹周長 108 cm，樹木直徑 34 cm 3
(Trimming) Perimeter of tree trunk 108cm, diameter of the tree 34cm

施工前照片2 Photos before construction2



(修剪) 樹幹周長 99 cm，樹木直徑 31 cm 4
(Trimming) Perimeter of tree trunk 99cm, diameter of the tree 31cm

施工前照片1 Photos before construction1



(砍除) 樹幹周長 52 cm，樹木直徑 16 cm ∇
(Felling) Perimeter of tree trunk 52cm, diameter of the tree 16cm

施工前照片2 Photos before construction2



(砍除) 樹幹周長 80 cm，樹木直徑 25 cm ∇
(Felling) Perimeter of tree trunk 80cm, diameter of the tree 25cm

附件：施工照片 Attachments: Photos of construction

施工前照片1 Photos before construction1



施工前照片2 Photos before construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工後照片1 Photos after construction1



施工後照片2 Photos after construction2



