



施工前照片1 Photos before construction1



樹幹周長 88 cm，樹木直徑 28 cm 
Perimeter of tree trunk 88cm, diameter of the tree 28cm

施工前照片2 Photos before construction2



樹幹周長 75 cm，樹木直徑 23 cm 
Perimeter of tree trunk 75cm, diameter of the tree 23cm

施工前照片1 Photos before construction1



樹幹周長 89 cm，樹木直徑 28 cm ③
Perimeter of tree trunk 89cm, diameter of the tree 28cm

施工前照片2 Photos before construction2



樹幹周長 49 cm，樹木直徑 15 cm
Perimeter of tree trunk 49cm, diameter of the tree 15cm

施工前照片1 Photos before construction1



樹幹周長 41 cm，樹木直徑 13 cm ✓
Perimeter of tree trunk 41cm, diameter of the tree 13cm

施工前照片2 Photos before construction2



樹幹周長 69 cm，樹木直徑 21 cm ④
Perimeter of tree trunk 69cm, diameter of the tree 21cm

施工前照片1 Photos before construction1



樹幹周長 34 cm，樹木直徑 10 cm 3
Perimeter of tree trunk 34cm, diameter of the tree 10cm

施工前照片2 Photos before construction2



樹幹周長 62 cm，樹木直徑 19 cm 4
Perimeter of tree trunk 62cm, diameter of the tree 19cm

附件：施工照片 Attachments: Photos of construction

施工前照片1 Photos before construction1



施工前照片2 Photos before construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工中照片1 Photos during construction1



施工中照片2 Photos during construction2



施工後照片1 Photos after construction1



施工後照片2 Photos after construction2



施工後照片1 Photos after construction1



施工後照片2 Photos after construction2



施工後照片1 Photos after construction1



施工後照片2 Photos after construction2



